


# GPS Perimeter Inspections

## Can you prove that your boundary is secure?

 Daredevil cliff jumpers somersault and back flip 63ft into flooded quarry where 25 have died since 1970s  
Mirror.co.uk - 11 Jun 2017

“The regulations require the operator to ensure that, where appropriate, properly maintained and suitable barriers are provided around the boundary for the purpose of discouraging trespass.”

 Children urged not to dice with death  
Wigan Today - 25 Apr 2017  
A total of 24 people died as a result of getting into trouble in water in Wigan where one water-filled quarry ...



“Under section 151(2)(c) of the Mines and Quarries Act (MQA) any quarry (whether in the course of being worked or not) which does not have an efficient and properly maintained barrier, designed and constructed to prevent people from accidentally falling into the quarry, and which by reason of its accessibility from a road or public place constitutes a danger to members of the public, is deemed to be a statutory nuisance under the Environmental Protection Act. The local authority, not HSE, enforces this provision.”

The Health and Safety at Work Act 1974 requires that the employer makes sure that the conduct of his undertaking does not expose those who are not his employees, but who might nevertheless be affected by the undertaking, to risks, so far as is reasonably practicable.



Endorsed by the  
Mineral Products Association

The below example of a finished report shows the accuracy and undeniable value of this Perimeter monitoring programme, on active and closed sites alike.





Each label on the map is interactive, enabling you to quickly review your boundary and arrange for repairs.



# Contact Information

- Julian Bulley – Director
- 07773 367830 / [Julian@GPSinspections.com](mailto:Julian@GPSinspections.com)
  
- Andy Bull – Technical Director
- 07415 466692 / [Andy@GPSinspections.com](mailto:Andy@GPSinspections.com)
  
- Darren Burton – Director
- 07704 034275 / [Darren@GPSinspections.com](mailto:Darren@GPSinspections.com)